HTemp-1Wire - Humidity & Temperature sensor

Digital temperature and humidity sensor for indoor usage. The sensor is designed for using with the Poseidon, Ares, HWg-STE and other HW group products.

You can have several parallel sensors on one RJ11 sensor port. Each one sensor is identified by a unique serial number.

HTemp-1Wire 3m
-30°C to +80°C

HTemp-1Wire Box2
-10°C to +80°C

HTemp-1Wire Rack19
-10°C to +80°C

Technical parameters

- **Sensor measured range**   **-30°C / **-10°C **to +80°C**   (-22°F / 14°F to +176°F)
  0 - 100% RH   (Relative Humidity)

- Temp. sensor resolution   0.1 °C
- Temp. measuring accuracy   **± 0.8 °C** in range from +20°C to +40°C
  ± 1.3 °C (-10°C to +70°C)

- RH Accuracy   ± 5% RH, 20 - 80%RH non-condensing, 25 °C
- RH Linearity & Hysteresis   <3% RH typical, ±3% RH span maximum
- RH Repeatability   ±0.2% RH

- Communication   1-Wire bus (Data, GND, +5V) - RJ11

- **HTemp-1Wire 3m**
  - Probe dimension 78 x 9.5 x 6 mm, cable 3m
  - Montage drill 1x Ø3mm

- **HTemp-1Wire Rack19**
  - Probe dimension 83 x 44 x 18 mm, 2x RJ11, cable 3m included
  - Montage drill 2x Ø6mm

- **HTemp-1W Box2**
  - Probe dimension 80 x 68 x 31 mm, 2x RJ11, cable 3m included
  - Montage drill 2x Ø3mm

Sensors & Accessories

HTemp-1Wire 3m   **Temp-1Wire 1m**   **Temp-1Wire-Flat 3m**   **T-Box**

HTemp-1Wire Outdoor 3m   **Temp-Rack19**   **Temp-1Wire-Outdoor 3m**   **T-Box**

Temperature & Humidity sensors & Accessories

|	
HTemp-1Wire 3m	*Temperature & Humidity sensor (-30 to +80°C, 0 to 100% RH). 3 meter long cable with 1-Wire connector RJ11, encased in black covering.*
HTemp-1Wire Box2	*Temperature & Humidity sensor (-10 to +80°C, 0 to 100% RH). Boxed sensor designed for internal use, 2x RJ11 daisy-chainable 1-Wire, 3m cable included.*
HTemp-1Wire Rack19	*Temperature & Humidity sensor (-10 to +80°C, 0 to 100% RH). 1U rack mount housing, 2x RJ11 daisy-chainable 1-Wire, 3m cable included. Sensor designed for 19" rack cabinets.*
Humid-1Wire 1m / 3m / 10m	*Humidity sensor (0 to 100% RH) on a 1m / 3m / 10m long cable with 1-Wire connector RJ11, encased in black covering.*
HTemp-1Wire Outdoor 3m	*Temperature & Humidity outdoor sensor (-30 to +85°C, 0 to 100% RH). 3 meter long cable with 1-Wire connector RJ11. Sensor encased in outdoor metal tube.*
T-Box	Hub for connecting 1 to 5 sensors to 1-Wire bus (5x RJ11), 10 cm connecting cable.
T-Box2	Hub for connecting 1 or 2 sensors to 1-Wire sensors (RJ11), 3 m connecting cable.
Temp-1Wire 3m IP67	*Temperature sensor (-10°C to +80°C), on a 3 meter long cable with 1-Wire connector RJ11. Watertight (IP67) sensor probe, stainless steel 17241.*
Temp-1Wire 10m IP67	*Temperature sensor (-10°C to +80°C), on a 10 meter long cable with 1-Wire connector RJ11. Watertight (IP67) sensor probe, stainless steel 17241.*
Temp-1Wire 1m / 3m / 10m	*Temperature sensor (-10°C to +80°C), on a 1 / 3 / 10 meter long cable with 1-Wire connector RJ11, encased in white covering.*
Temp-1Wire-Outdoor 3m	*Temperature outdoor sensor (-50°C to +125°C) - Multi-purpose watertight (IP67) sensor probe, stainless steel 17241 with PVC cable 3m, 1-Wire connector RJ11.*
Temp-1Wire-Flat 3m	*Temperature sensor for freezers (-30 to +60°C), watertight (IP67) stainless steel 17241 probe, flat cable 3m, 1-Wire connector RJ11.*

Connectors

| RJ12	RJ11			
3	2	**Data**	<->	Data 1-Wire
4	3	**GND**	---	System Ground
5	4	**+5V**	---	Power supply

Sensors wiring examples

Star topology – 60m in total:

You can use the T-Box or T-Box2 splitters to connect more sensors to one device active port.

Daisy-chained – 60m in total:

There are **two RJ11 female connectors** on some sensors.

4x active port, 4x60m: